Joseph G. Reed Company (Fowler Building) 700 Second Street
Portsmouth
Scioto County
Ohio

HABS No. OH-665

HA89 OH10 73-PORT

PHOTOGRAPHS

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

HISTORIC AMERICAN BUILDINGS SURVEY
MID-ATLANTIC REGION NATIONAL PARK SERVICE
DEPARTMENT OF THE INTERIOR
PHILADELPHIA, PENNSYLVANIA 19106

Form 10-920 (June 1983)

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE



ARCHITECTURAL DATA FORM

<u></u>		· · · · · · · · · · · · · · · · · · ·			
STATE	COUNTY		TOWN OR VIC	WN OR VICINITY	
Ohio	Scioto Portsmout				
HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME)				HABS NO.	
Joseph G. Reed Company				OH-665	
SECONDARY OR COMMON NAMES OF STRUCTURE					
Fowler Building					
COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES)					
700 Second Street (Southeast corner of Second and Washington Streets					
DATE OF CONSTRUCTION (INCLUDE SOURCE) A.B. Algar & Sons (Indicated)				ed on original	
1906 Date on building at front entrance drawings - No. 170)				-	
SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE) The Joseph G. Reed Company is a relatively intact turn-of-the-century warehouse structure, important to the development of trade in the riverfront towns of the Ohio Valley.					
STYLE (IF APPROPRIATE) Romanesque influence					
MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS)					
rectangular 125' x 62 1/2' EXTERIOR FEATURES OF NOTE Three bay facade has two large plate glasswindows flanking a round-arched, recessed entrance (remodeled, with glass block and aluminum storefront). The upper floors (north and west elevations) have brick arcades with brick spandrel panels, paired windows (filled in with glass block) and raised brick quoins. The other two elevations are common brick. INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED) with little decoration. Brick detailing in the arcades and a simple cornice complete the building. MAJOR ALTERATIONS AND ADDITIONS WITH DATES					
PRESENT CONDITION AND USE Sound condition, with some Used as office-warehouse.		repair in upper	walls. Ir	nterior-poor condition	
OTHER INFORMATION AS APPROPRIATE Structure to be rehabilitated to develop housing units for elderly.					
SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.)					
Partial set of original bl partial plans drawn by Pau	ueprints by Al 1 E. Fowler, d	ger & Sons (1906 ated 7/9/46; Ohi	?), possibl o Historic	y remodeling drawings Inventory form	
COMPILER, AFFILIATION Robert D Associates. (Transcribed	. Loversidge, A	AIA, Schooley Cal rper, Consultant	ldwell	DATE November 1980	

